


HMTD3
est conçu pour l'enlèvement de
tarauds cassés.




FRESAL				D	L	LT	d
FILETTO	UNCOATED	MAXTOP	CODES	e9			h6
M3	⊙	-	HMTD3M03	2,5	12	50	6
M4	⊙	-	HMTD3M04	3,3	15	50	6
M5	⊙	-	HMTD3M05	4,2	15	50	6
M6	⊙	-	HMTD3M06	5,0	15	50	6
M8	⊙	-	HMTD3M08	6,8	20	63	8
M10	⊙	-	HMTD3M10	8,5	25	72	10
M12	⊙	-	HMTD3M12	10,2	30	83	12
M14	⊙	-	HMTD3M14	12,0	30	83	12
M16	⊙	-	HMTD3M16	14,0	40	100	14
M18	⊙	-	HMTD3M18	15,5	40	100	16
M20	⊙	-	HMTD3M20	17,5	50	100	18

Grâce à la géométrie de
construction extra négative,
ces outils peuvent être utilisés
non seulement pour enlever
des tarauds cassés,
mais aussi pour percer des
matériaux difficiles.




DISTRUCTEURS DE TARAUDS *4 faces*



FRESAL
UTENSILI

HMTD4

est conçu pour l'enlèvement
de tarauds cassés.



FRESAL				D	L	LT	d
FILETTO	UNCOATED	MAXTOP	CODES	e9			h6
M3	⊙	-	HMTD4M03	2,5	12	50	6
M4	⊙	-	HMTD4M04	3,3	15	50	6
M5	⊙	-	HMTD4M05	4,2	15	50	6
M6	⊙	-	HMTD4M06	5,0	15	50	6
M8	⊙	-	HMTD4M08	6,8	20	63	8
M10	⊙	-	HMTD4M10	8,5	25	72	10
M12	⊙	-	HMTD4M12	10,2	30	83	12
M14	⊙	-	HMTD4M14	12,0	30	83	12
M16	⊙	-	HMTD4M16	14,0	40	100	14
M18	⊙	-	HMTD4M18	15,5	40	100	16
M20	⊙	-	HMTD4M20	17,5	50	100	18

Grâce à la géométrie de
construction extra négative,
ces outils peuvent être utilisés
non seulement pour enlever
des tarauds cassés,
mais aussi pour percer des
matériaux difficiles